

31/OFFER/2022



Producer	Mercedes Benz - VAN
Model	519 CDI 190 KM
Specification	Stock vehicle
Transmission	Automatic
External lights	Original LED Performance - Front - Rear
VIN	Sprinter No. 487
Number of passengers	25+1+1

Selected equipment

BODY WORK

- **Extension** - Extension between axels + back
- **Roof** - Roof hatch - Manual
- **Windows**
 - Side - Fake panoramic double
 - Front - Original
- **Doors**
 - Side - Emergency

- Electric - Front
 - Rear - Original without glasses
 - **Lifting** - Small Lifting
 - **Bumper**
 - Front - Cuby Sport - Diamond
 - Back - Rear Original
 - **Seats mounting** - Floor - wall
 - **Trunks** - Rear - Deepened with preparation for the hook
 - **Seat platforms** - Full
-

PAINTING

- **Colour:** navy blue metallic
-

ROOF AIR-CONDITIONING

- **Distribution** - In shelves
-

SHELVES

- **Standard** - With A/C chanel
 - **Service sets: vent, light, speaker:** with RGB LED lighting
 - Colour - Black
 - Material between service sets - Black
-

UPHOLSTERY


- **Colour** - Black
 - **Ceiling** - Material
 - **Sides**
 - Material - Soft / textile
 - Colour - Black
 - Structure - Plain
 - **Dashboard** - Covered in leather
 - **Covering:** wood imitation
 - **Laths under and above the windows:** carbon imitation
 - **Curtains**
-

ELECTRICAL AND ASSEMBLY

- **Lighting**
- Ceiling - LED standard
- Above and under windows - LED standard
- Seat platforms - LED standard
- Entrance step
 - Logo
 - LED standard
- External halogen
 - Rear
 - Front
- **Audio**
- Additional speakers

- Subwoofer
- Amplifier
- Radio - 2 Din
- Microphone
- **Heating**
- Convector heating
- Electric heater
- **Seats**
- Scheme (Attachment 1)
- Seat cushion - 40
- Features of the seat
 - Newspaper net
 - Table
 - Handles
 - Armrest
 - Side sliding
 - PET
 - Safety belts - 3 pointed
- Backrest - Adjustable
- Legs - Standard
- **Additional equipment**
- Chrome hubcaps
- Carpets
 - Corridor
 - Under the seats
 - Entrance steps
- USB port - Quantity and place - in shelves, 1x for each row of seats, 2x in the dashboard
- School signs
- Camera - Rear
- STOP Button
- Marker lamps
- Reverse gear horn
- School norms
- Wall behind driver - Lack of table
- LED directional display - Place of installation - on the windshield
- Railings
- **Towing hook**
- **Other additional equipment** : setra line on the side windows

Attachments



Attachment 1 - Seats - Scheme